PURCHASES MADE FROM THIS LIST MAY NOT EXCEED \$500,000 PER PROJECT. Customers must solicit quotations from two or more sellers regardless of the dollar amount.

RYAN PUBLIC SAFETY SOLUTIONS

Non-ARRA Participant

Main Sales Contact

Marissa Hare

Office: (260) 469-2122 Email: Mhare@indigital.net

Backup Sales Contact

Jim Fleming

Office: (256) 425-6568

Email: jim.fleming@rpss911.com

Place Order To:	Remit To:
Ryan Public Safety Solutions	Ryan Public Safety Solutions
12119 US Highway 431	12119 US Highway 431
Guntersville, AL 35976	Guntersville, AL 35976

Hourly rates for service published with this list may only be used in conjunction with equipment purchased from this list.

Hourly Rate Description	Not-to-Exceed Service Rates
Basic Installation Services	\$85
Project Manager/Engineer/Advanced Technical	\$120
Maintenance and Support	\$100
Training	\$100
Travel	\$85

COMPANY NAME	Ryan Public Safety Solutions			
Configuration # 1	Type and Number of Positions: 2 Positions	. up to 6 trunks		
Manufacturer and	- 7,	,		
System Name:	Motorola VESTA			
Manufacturer of		Purchase Part		
Component	Description of Component	Number		
MOTOROLA	VESTA SERVER BACKROOM	853031-MLBRSSG		
MOTOROLA	VESTA WORKSTATION	853031-ESSLTWKST		
HEWLETT PACKARD	VESTA MANAGEMENT CONSOLE	61000-819206		
WALKER	WORKSTATION HANDSET & CORD	02800-20500		
CISCO	LAN SWITCH, 24 PORT	04000-29616		
CISCO	SECURE FIREWALL	RP-AS5506		
INTEGRATED	IC6911S ALI DATABASE MODEM	RP-IC6911S		
COMMUNICATIONS				
TNT SOFTWARE	CLASS I SERVER LICENSE	RP-551200		
TNT SOFTWARE	CLASS II DEVICE LICENSE	RP-551300		
WESTERN DIGITAL	NETWORK ATTACHED STORAGE	RP-NAS		
BLACK BOX	BLACK BOX DATACAST, 8 PORT	04000-00159		
BLACK BOX	CABLE ADAPTER FOR DATACAST	65000-00262		
VERTIV	LIEBERT 3KVA UPS	RP-LGXT4		
CYBERPOWER	CYBERPOWER CP1500VA	RP-CP1500		
MOTOROLA	CDR PRINTER WITH CABLES	04000-00420		
MOTOROLA	VESTA BACKROOM SUPPORT 1 YR	853031-BRSGSPT1YR		
MOTOROLA	VESTA WORKSTATION SUPPORT 1 YR	853031-ESSLTWKST1YF		
Cost of System when p	oriced as a turnkey system. Includes all engine	ering, cabling,		
installation, training ar		0 ,	\$102,800.00	
	Description of Installation Servi	ces		
Turnkey 2 Position Vol	P 9-1-1 Call Taking Solution with the capability	to support up to 6		
1	ncludes installation, training, and first year of su			
	luded in the turnkey price (The cost for installat		Installation	
	if the customer does not wish to purchase insta	•	Required	
	Description of Training Service			
Training includes one of	administrative class for supervisors; typically las			
-	ip to six students per class is also included; 4 h			
training materials will b	·	ours per class. All		
	•	y he removed from the		
	ed in the turnkey price (The cost for training ma tomer does not wish to purchase training unles:	•	Training	
Vendor)	tomer does not wish to purchase training unless	s required by the	Training Required	
veridor)	Description of Base Warranty of Turnk	ov Systom	Required	
Included 1 was a of O4.		, ,	1	
•	7x365 support services with remote alarm monit	toring, parts, labor and		
lightning damage.				
Enhanced Warranty or Post-Warranty Maintenance Options			0. 1	
Provided by	Description VEGET AVEAU		Cost	
MOTOROLA	VESTA SOFTWARE SUPPORT, 1 YEAR		\$2,880.00	
RPSS	ON-SITE SUPPORT/MAINTENANCE, 1 YEAF	(\$9,200.00	

COMPANY NAME	Ryan Public Safety Solutions	
Configuration # 1	Type and Number of Positions: 2 Positions, up to 6 trunks	
Manufacturer and	Type and Namber of Fositions. 2 Fositions, up to o trained	
	Motorola VESTA	
HEWLETT PACKARD	EXTENDED SERVER COMPUTER WARRANTY, 5 YEAR	\$2,580.00
HEWLETT PACKARD	EXTENDED WORKSTATION COMPUTER WARRANTY, 5 YEAR	\$1,245.00

COMPANY NAME	Ryan Public Safety Solutions		
Configuration # 2	Type and Number of Positions: 2 Position	ons, up to 6 trunks	
Manufacturer and			
System Name:	Motorola VESTA with Mapping		
Manufacturer of	, , , , , , , , , , , , , , , , , , ,	Purchase Part	
Component	Description of Component	Number	
MOTOROLA	VESTA SERVER BACKROOM	853031-MLBRSSG	
MOTOROLA	VESTA WORKSTATION	853031-ESSLTWKST	
HEWLETT PACKARD	VESTA MANAGEMENT CONSOLE	61000-819206	
HEWLETT PACKARD	MAP MONITOR, 20IN	63000-202901	
MOTOROLA	MAP LOCAL GIS SERVICES	809800-44119	
WALKER	WORKSTATION HANDSET & CORD	02800-20500	
CISCO	LAN SWITCH, 24 PORT	04000-29616	
CISCO	SECURE FIREWALL	RP-AS5506	
INTEGRATED	IC6911S ALI DATABASE MODEM	RP-IC6911S	
COMMUNICATIONS			
TNT SOFTWARE	CLASS I SERVER LICENSE	RP-551200	
TNT SOFTWARE	CLASS II DEVICE LICENSE	RP-551300	
WESTERN DIGITAL	NETWORK ATTACHED STORAGE	RP-NAS	
BLACK BOX	BLACK BOX DATACAST, 8 PORT	04000-00159	
BLACK BOX	CABLE ADAPTER FOR DATACAST	65000-00262	
VERTIV	LIEBERT 3KVA UPS	RP-LGXT3	
CYBERPOWER	CYBERPOWER CP1500VA	RP-CP1500	
MOTOROLA	CDR PRINTER WITH CABLES	04000-00420	
MOTOROLA	VESTA BACKROOM SUPPORT 1 YR	853031-BRSGSPT1YR	
MOTOROLA	VESTA WORKSTATION SUPPORT 1 YR	853031-ESSLTWKST1YR	
Cost of System when priced as a turnkey system. Includes all engineering, cabling,			\$113,200.00
installation, training ar	nd lightning protection.	-	
·	Description of Installation Se	rvices	
Turnkey 2 Position Vol	P 9-1-1 Call Taking Solution with the capabi	lity to support up to 6	
•	ncludes installation, training, and first year o	•	
	cluded in the turnkey price (The cost for insta		Installation
	if the customer does not wish to purchase in		Required
nom the turney price	Description of Training Serv	· · · · · · · · · · · · · · · · · · ·	rtequired
Training includes one			1
_	administrative class for supervisors; typically	•	
	up to six students per class is also included;	4 nours per class. All	
training materials will b	<u> </u>		
	ed in the turnkey price (The cost for training	•	Training
turnkey price if the cus	tomer does not wish to purchase training un	less required by the	Required
	Description of Base Warranty of Tur	nkey System	
Includes 1 year of 24x7	7x365 support services with remote alarm mo	onitoring, parts, labor and	
lightning damage.		3,1	
ng.m.n.g asinagai	Enhanced Warranty or Post-Warranty Ma	intenance Ontions	
Provided by	Provided by Description		Cost
MOTOROLA	VESTA SOFTWARE SUPPORT, 1 YEAR		\$3,610.00
RPSS	ON-SITE SUPPORT/MAINTENANCE, 1 YEAR		\$9,700.00
HEWLETT PACKARD	EXTENDED SERVER COMPUTER WARRANT	Y 5 YEAR	\$2,580.00
HEWLETT PACKARD	EXTENDED WORKSTATION COMPUTER WA		
HEWLETT PACKARD	EXTENDED WORKSTATION COMPUTER WA	NANII, DIEAK	\$1,245.00

COMPANY NAME	Ryan Public Safety Solutions		
Configuration # 3	Type and Number of Positions: 3 Position	one un to 6 trunke	
Manufacturer and	Type and Number of Fositions. Of osition	ons, up to o trunks	
System Name:	 Motorola VESTA		
Manufacturer of	INICIOIOIA VESTA	Purchase Part	
	Description of Component	Number	
Component	Description of Component VESTA SERVER BACKROOM		
MOTOROLA MOTOROLA		853031-MLBRSSG	
HEWLETT PACKARD	VESTA WORKSTATION VESTA MANAGEMENT CONSOLE	853031-ESSLTWKST	
WALKER	WORKSTATION HANDSET & CORD	61000-819206 02800-20500	+
CISCO	LAN SWITCH, 24 PORT	04000-29616	1
CISCO	SECURE FIREWALL	RP-AS5506	
INTEGRATED	IC6911S ALI DBASE MODEM	RP-IC6911S	
COMMUNICATIONS	1003110 ALI BBAGE MODEM	111 -1009110	
TNT SOFTWARE	CLASS I SERVER LICENSE	RP-551200	
TNT SOFTWARE	CLASS II DEVICE LICENSE	RP-551300	
WESTERN DIGITAL	NETWORK ATTACHED STORAGE	RP-NAS	
BLACK BOX	BLACK BOX DATACAST, 8 PORT	04000-00159	
BLACK BOX	CABLE ADAPTER FOR DATACAST	65000-00262	
VERTIV	LIEBERT 3KVA UPS	RP-LGXT3	
CYBERPOWER	CYBERPOWER CP1500VA	RP-CP1500	
MOTOROLA	CDR PRINTER WITH CABLES	04000-00420	
MOTOROLA	VESTA BACKROOM SUPPORT 1 YR	853031-BRSGSPT1YR	
MOTOROLA	VESTA WORKSTATION SUPPORT 1 YR	853031-ESSLTWKST1YR	
Cost of System when r	oriced as a turnkey system. Includes all engi	neering, cabling.	
installation, training ar			\$112,500.00
incommunity and incoming an	Description of Installation Se	rvices	* 1 12,000 100
	·		1
Turnkey 2 Position Vol	P 9-1-1 Call Taking Solution with the capabil	ity to support up to 6	
trunks. Configuration i	includes installation, training, and first year o	f support services.	
Ţ.	cluded in the turnkey price (The cost for insta		Installation
	if the customer does not wish to purchase in		Required
, , , , , , , , , , , , , , , , , , , ,	Description of Training Serv		1 1 1 1 1 1 1
Tueining in alude a succ			1
_	administrative class for supervisors; typically	•	
	up to six students per class is also included;	4 hours per class. All	
training materials will b	pe provided by RPSS.		
Cost for training includ	ed in the turnkey price (The cost for training	may be removed from the	
	tomer does not wish to purchase training un	•	Training
Vendor)		,	Required
v ender/	Description of Base Warranty of Tur	nkev System	i toquii ou
Includes 1 year of 24v	7x365 support services with remote alarm mo		1
lightning damage.	7 X303 Support Services with remote diamin in	ormoring, parts, labor and	
ilgritining damage.	Enhanced Morrouts or Doct Morrouts No	intenence Ontions	
Enhanced Warranty or Post-Warranty Maintenance Options			0 1
Provided by	Description VEAR		Cost
MOTOROLA	VESTA SOFTWARE SUPPORT, 1 YEAR		\$3,952.00
RPSS	ON-SITE SUPPORT/MAINTENANCE, 1 YEAR	V E VEAD	\$9,700.00
HEWLETT PACKARD	EXTENDED WORKSTATION COMPUTER WARRANT	·	\$2,580.00
HEWLETT PACKARD	EXTENDED WORKSTATION COMPUTER WAI	KKANIY, 5 YEAK	\$1,658.00

COMPANY NAME	Ryan Public Safety Solutions		
Configuration # 4	Type and Number of Positions: 3 Position	ns, up to 6 trunks	
Manufacturer and	7,	-,	
System Name:	Motorola VESTA with Mapping		
	With Wapping	Purchase Part	
Manufacturer of	D		
Component	Description of Component	Number	
MOTOROLA	VESTA SERVER BACKROOM	853031-MLBRSSG	
MOTOROLA	VESTA WORKSTATION	853031-ESSLTWKST	
HEWLETT PACKARD	VESTA MANAGEMENT CONSOLE	61000-819206	
HEWLETT PACKARD	MAP MONITOR, 20IN	63000-202901	
MOTOROLA	MAP LOCAL GIS SERVICES	809800-44119	
WALKER	WORKSTATION HANDSET & CORD	02800-20500	
CISCO	LAN SWITCH, 24 PORT	04000-29616	
CISCO	SECURE FIREWALL	RP-AS5506	
INTEGRATED COMMUNICATIONS	IC6911S ALI DBASE MODEM	RP-IC6911S	
TNT SOFTWARE	CLASS I SERVER LICENSE	RP-551200	
TNT SOFTWARE	CLASS II DEVICE LICENSE	RP-551300	
WESTERN DIGITAL	NETWORK ATTACHED STORAGE	RP-NAS	
BLACK BOX	BLACK BOX DATACAST, 8 PORT	04000-00159	
BLACK BOX	CABLE ADAPTER FOR DATACAST	65000-00262	
VERTIV	LIEBERT 3KVA UPS	RP-LGXT3	
CYBERPOWER	CYBERPOWER CP1500VA	RP-CP1500	
MOTOROLA	CDR PRINTER WITH CABLES	04000-00420	•
MOTOROLA	VESTA MODICOTATION SUPPORT 1 YR	853031-BRSGSPT1YR	
MOTOROLA Cost of System when a	VESTA WORKSTATION SUPPORT 1 YR	853031-ESSLTWKST1YR	
installation, training ar	oriced as a turnkey system. Includes all engi	neering, cabiing,	\$127,600.00
installation, training at	Description of Installation Se	rvices	\$127,600.00
Tumples (O. Danitian Ma	·		1
	IP 9-1-1 Call Taking Solution with the capabil includes installation, training, and first year of		
Cost for Installation inc	cluded in the turnkey price (The cost for insta	llation may be removed	Installation
· · · · · · · · · · · · · · · · · · ·	if the customer does not wish to purchase in	<u> </u>	Required
mont the tarricey price	Description of Training Serv	,	, to quii o u
	·		1
_	administrative class for supervisors; typically		
calltaker classes with t	up to six students per class is also included; 4	l hours per class. All	
training materials will b	pe provided by RPSS.		
Cost for training includ	ed in the turnkey price (The cost for training	may be removed from the	
	stomer does not wish to purchase training unl	•	Training
Vendor)	nomer does not wish to paronase training and	cos required by the	Required
vendor)	Description of Description of Ton		
	Description of Base Warranty of Tur	nkey System	1
Includes 1 year of 24x	7x365 support services with remote alarm mo	onitoring, parts, labor and	
lightning damage.		5 .1	
Enhanced Warranty or Post-Warranty Maintenance Options			
Provided by	Description		Cost
MOTOROLA	VESTA SOFTWARE SUPPORT, 1 YEAR		\$4,965.00
RPSS	ON-SITE SUPPORT/MAINTENANCE, 1 YEAR		\$10,200.00
HEWLETT PACKARD	EXTENDED SERVER COMPUTER WARRANT	/, 5 YEAR	\$2,580.00

Vendor Configurations and Component Pricing Product and Pricing Revised: 05-31-2019

COMPANY NAME	Byon Bublic Sefety Solutions	
COMPANT NAME	Ryan Public Safety Solutions	
Configuration # 4	Type and Number of Positions: 3 Positions, up to 6 trunks	
Manufacturer and		
System Name:	Motorola VESTA with Mapping	
HEWLETT PACKARD	EXTENDED WORKSTATION COMPUTER WARRANTY, 5 YEAR	\$1,658.00

COMPANY NAME	Ryan Public Safety Solutions		
Configuration # 5	Type and Number of Positions: 4 Position	s un to 8 trunks	
Manufacturer and		o, up to o traine	
System Name:	Motorola VESTA		
Manufacturer of	INICIOICA VECTA	Purchase Part	
Component	Description of Component	Number	
<u>-</u>	•		
MOTOROLA MOTOROLA	VESTA WORKSTATION	853031-MLBRSSG 853031-ESSLTWKST	
HEWLETT PACKARD	VESTA WORKSTATION VESTA MANAGEMENT CONSOLE	61000-819206	
WALKER	WORKSTATION HANDSET & CORD	02800-20500	
CISCO	LAN SWITCH, 24 PORT	04000-29616	
CISCO	SECURE FIREWALL	RP-AS5506	
INTEGRATED	IC6911S ALI DBASE MODEM	RP-IC6911S	
COMMUNICATIONS			
TNT SOFTWARE	CLASS I SERVER LICENSE	RP-551200	
TNT SOFTWARE	CLASS II DEVICE LICENSE	RP-551300	
WESTERN DIGITAL	NETWORK ATTACHED STORAGE	RP-NAS	
BLACK BOX	BLACK BOX DATACAST, 8 PORT	04000-00159	
BLACK BOX	CABLE ADAPTER FOR DATACAST	65000-00262	
VERTIV	LIEBERT 3KVA UPS	RP-LGXT3	
CYBERPOWER	CYBERPOWER CP1500VA	RP-CP1500	
MOTOROLA	CDR PRINTER WITH CABLES	04000-00420	
MOTOROLA	VESTA BACKROOM SUPPORT 1 YR	853031-BRSGSPT1YR	
MOTOROLA	VESTA WORKSTATION SUPPORT 1 YR	853031-ESSLTWKST1YR	
Cost of System when priced as a turnkey system. Includes all engineering, cabling,			
installation, training ar	nd lightning protection.		\$120,400.00
	Description of Installation Serv	/ices	
Turnkey 2 Position Vol	IP 9-1-1 Call Taking Solution with the capability	y to support up to 6	
trunks. Configuration i	includes installation, training, and first year of s	support services.	
Cost for Installation inc	cluded in the turnkey price (The cost for installa	ation may be removed	Installation
· · · · · · · · · · · · · · · · · · ·	if the customer does not wish to purchase inst	-	Required
, ,	Description of Training Service		
Training includes one	administrative class for supervisors; typically la		
_	up to six students per class is also included; 4 l	•	
training materials will b	·	nours per class. All	
	<u> </u>	and has represented from the	
	ed in the turnkey price (The cost for training m	•	- · ·
· · ·	tomer does not wish to purchase training unles	ss required by the	Training
Vendor)			Required
	Description of Base Warranty of Turn	key System	
Includes 1 year of 24x7x365 support services with remote alarm monitoring, parts, labor and			
lightning damage.			
		Lenance Oblions	
Ducyddad by	Enhanced Warranty or Post-Warranty Main		Coot
Provided by	Description		Cost
MOTOROLA	Description VESTA SOFTWARE SUPPORT, 1 YEAR		\$4,940.00
MOTOROLA RPSS	Description VESTA SOFTWARE SUPPORT, 1 YEAR ON-SITE SUPPORT/MAINTENANCE, 1 YEAR	·	\$4,940.00 \$10,200.00
MOTOROLA	Description VESTA SOFTWARE SUPPORT, 1 YEAR	5 YEAR	\$4,940.00

COMPANY NAME	Ryan Public Safety Solutions		
Configuration # 6	Type and Number of Positions: 4 Positions	e un to 8 trunke	
Manufacturer and	Type and Namber of Fositions: 41 ositions	s, up to o truins	
System Name:	Motorola VESTA with Mapping		
Manufacturer of	iniotoroid 1201/t tritis inapping	Purchase Part	
Component	Description of Component	Number	
MOTOROLA	VESTA SERVER BACKROOM	853031-MLBRSSG	
MOTOROLA	VESTA WORKSTATION	853031-ESSLTWKST	
HEWLETT PACKARD	VESTA MANAGEMENT CONSOLE	61000-819206	
HEWLETT PACKARD	MAP MONITOR, 20IN	63000-202901	
MOTOROLA	MAP LOCAL GIS SERVICES	809800-44119	
WALKER	WORKSTATION HANDSET & CORD	02800-20500	
CISCO	LAN SWITCH, 24 PORT	04000-29616	
CISCO	SECURE FIREWALL	RP-AS5506	
INTEGRATED	IC6911S ALI DBASE MODEM	RP-IC6911S	
COMMUNICATIONS TNT SOFTWARE	CLASS I SERVER LICENSE	RP-551200	
TNT SOFTWARE	CLASS I DEVICE LICENSE	RP-551300	
WESTERN DIGITAL	NETWORK ATTACHED STORAGE	RP-NAS	
BLACK BOX	BLACK BOX DATACAST, 8 PORT	04000-00159	
BLACK BOX	CABLE ADAPTER FOR DATACAST	65000-00262	
VERTIV	LIEBERT 3KVA UPS	RP-LGXT3	
CYBERPOWER	CYBERPOWER CP1500VA	RP-CP1500	
MOTOROLA	CDR PRINTER WITH CABLES	04000-00420	
MOTOROLA	VESTA BACKROOM SUPPORT 1 YR	853031-BRSGSPT1YR	
MOTOROLA	VESTA WORKSTATION SUPPORT 1YR	853031-ESSLTWKST1YR	
Cost of System when p	oriced as a turnkey system. Includes all engine	eering, cabling,	
installation, training ar	<u> </u>		\$142,300.00
	Description of Installation Serv	ices	
Turnkev 2 Position Vol	P 9-1-1 Call Taking Solution with the capability	to support up to 6	
•	ncludes installation, training, and first year of s		
	cluded in the turnkey price (The cost for installa	• •	Installation
	if the customer does not wish to purchase insta	-	Required
nom the tarricey price			rtoquirou
	Description of Training Service		
_	administrative class for supervisors; typically la	_	
	ıp to six students per class is also included; 4 h	nours per class. All	
training materials will b	e provided by RPSS.		
Cost for training includ	ed in the turnkey price (The cost for training ma	ay be removed from the	Training
turnkey price if the customer does not wish to purchase training unless required by the			Required
	Description of Base Warranty of Turnl		
Includes 1 year of 24x	7x365 support services with remote alarm mon	itoring, parts, labor and	
lightning damage.			
	Enhanced Warranty or Post-Warranty Maint	tenance Options	
Provided by	Description		Cost
MOTOROLA	VESTA SOFTWARE SUPPORT, 1 YEAR		\$6,505.00
RPSS	ON-SITE SUPPORT/MAINTENANCE, 1 YEAR		\$10,700.00

COMPANY NAME	Ryan Public Safety Solutions	
Configuration # 6	Type and Number of Positions: 4 Positions, up to 8 trunks	
Manufacturer and	- Type and talking the control of th	
System Name:	Motorola VESTA with Mapping	
HEWLETT PACKARD	EXTENDED SERVER COMPUTER WARRANTY, 5 YEAR	\$2,580.00
HEWLETT PACKARD	EXTENDED WORKSTATION COMPUTER WARRANTY, 5 YEAR	\$2,074.00

COMPANY NAME				
	Ryan Public Safety Solutions COMPONENTS LIST			
Provider of	Description of Component	Purchase Part Number	Purchase	
Service or		of Component	Cost	
Manufacturer of		or compension		
Component				
MOTOROLA	GEO-DIVERSIFICATION OF SYSTEM	RP-VGEODIV	\$26,000.00	
MOTOROLA	EQUIPMENT CABINET FOR BACKROOM	00600-20042	\$7,360.00	
HEWLETT				
PACKARD	VESTA SERVER, TOWER	62030-M819204	\$3,764.00	
MICROSOFT	WINDOWS SERVER SOFTWARE	04000-00438	\$1,296.00	
PERLE SYSTEMS	IOLAN DEVICE, SERVER 4 PORT	04000-01757	\$678.00	
PERLE SYSTEMS	ADAPTER RJ45F/DB25M	04000-31281	\$24.00	
MOTOROLA	VESTA WORKSTATION BUNDLE	853031-ESSLTWKST	\$7,006.00	
MOTOROLA	VESTA WRKSTN SOFTWARE SUPPORT, 1 YR	853031-ESSLTWKST1YR	\$1,065.00	
MOTOROLA				
	VESTA WORKSTATION BUNDLE WITH MAPPING	853031-ESSLTMPWKST	\$9,750.00	
MOTOROLA	VESTA WRKSTN BUNDLE W/ MAPPING	853031-		
	SOFTWARE SUPP, 1 YR	ESSLTMPWKST1YR	\$1,458.00	
HEWLETT				
PACKARD	MANAGEMENT CONSOLE, DESKTOP ELITE MINI	61000-409604	\$694.00	
MICROSOFT	WINDOWS SOFTWARE LICENSE	04000-30441	\$119.00	
HEWLETT			•	
PACKARD	WORKSTATION DKTP PRODESK MINI	61000-819206	\$1,120.00	
HEWLETT		0.000 0.0200	ψ1,120.00	
PACKARD	DKTP TOWER STAND	64000-00200	\$30.00	
HEWLETT	DRIT TOTAL CONTROL	0.000 00200	Ψ00.00	
PACKARD	MNTR FP WIDE SCR LCD 22IN	63000-221693	\$296.00	
GENOVATION	KEYPAD 24KEY 12FT CBL	64007-50021	\$140.00	
MOTOROLA	SAM EXT SPKR KIT	853004-00401	\$218.00	
MOTOROLA	SAM PC SPKR KIT	853004-00701	\$60.00	
MOTOROLA	SAM HDWR KIT	853030-00302	\$2,147.00	
WALKER	HANDSET	02800-20700	\$32.00	
WALKER	HANDSET CORD, 12FT	03044-20000		
MOTOROLA	HANDSET CORD, 12FT	03044-20000	\$4.00	
INIOTOROLA	WORKSTATION CONFIGURATION & STAGING FEE	800800 35100	¢560.00	
	WORKSTATION CONFIGURATION & STAGING FEE	809800-33109	\$560.00	
HEWLETT	CDOST LADTOD	61050-G819604	¢0.400.00	
PACKARD	CPOST LAPTOP	61050-G619604	\$2,408.00	
HEWLETT	ODOCT DOCKING STATION	05000 00000	0040.00	
PACKARD	CPOST DOCKING STATION	65000-00263	\$648.00	
HEWLETT			*=0.00	
PACKARD	CPOST KEYBOARD/MOUSE BUNDLE	64021-10025	\$56.00	
MOTOROLA	CPOST SAM HDWR KIT	853004-00302	\$2,498.00	
MOTOROLA	CPOST CONFIG & STG FEE	809800-35108	\$560.00	
MOTOROLA	VESTA IRR LIC/DOC/MED	873099-00502	\$1,274.00	
MOTOROLA	VESTA IRR SW SPT 1YR	809800-35110	\$210.00	
MOTOROLA	PRNTR USB B/W LASERJET	64040-60020	\$460.00	
MOTOROLA	IP PHN LIC ENHANCED	873010-00202	\$384.00	
MITEL	IP PHONE SET	04000-06757	\$400.00	
MITEL	IP PHONE SET EXPANSION MODULE	04000-01675	\$275.00	
MOTOROLA	IP PHN CFG FEE PER PHN	809800-10201	\$62.00	

COMPANY NAME	Ryan Public Safety Solutions			
COMPONENTS LIST				
Provider of	Description of Component	Purchase Part Number	Purchase	
Service or		of Component	Cost	
Manufacturer of		o. component		
Component	VEOTA VIALLO DED MAIL DOV	070040 00400	400.00	
MOTOROLA	VESTA VM LIC PER MAILBOX	873010-00402	\$62.00	
MOTOROLA	VESTA ANALYTICS LITE USER LICENSE	873391-04002	\$480.00	
MOTOROLA	VESTA ANALYTICS LITE PER SEAT LICENSE	PA-SSG-ALSL	\$704.00	
MOTOROLA	VESTA ANALYTICS LITE ADD ON HARDWARE	SA-SSG-ALSL-1Y	\$116.00	
MOTOROLA	VESTA ANALYTICS LITE ADD-ON HARDWARE	DA MOO AL AO 2	¢4 400 00	
MOTODOLA	BUNDLE	BA-M00-ALA0-3	\$1,498.00	
MOTOROLA	VESTA ANALYTICS STD LICENSE	973391-00501	\$2,560.00	
MOTOROLA	VESTA ANALYTICS STD DER SEAT LICENSE	873391-00301	\$960.00	
MOTOROLA	VESTA ANALYTICS STD PER SEAT LICENSE	PA-MSG-ASSL	\$832.00	
MOTOROLA	VESTA ANLYTICS STD SUPPORT, 1 YR	SA-MSG-ALSL-1Y	\$138.00	
MOTOROLA	VESTA ACTIVITY VIEW SEAT LICENSE	873099-00802	\$960.00	
MOTOROLA	VESTA ACTIVITY VIEW SITE LICENSE	873099-00702	\$4,480.00	
MOTOROLA	VESTA ACTIVITY VIEW SOFTWARE SUPPORT, 1YR	809800-35120	\$742.00	
CISCO	LAN SWITCH 2960-PLUS 24 PORT	04000-29616	\$1,228.00	
CISCO	WARRANTY FOR 2960 PLUS, 1YR	04000-02991	\$314.00	
CISCO	LAN SWITCH/POE 2960 24 PORT	04000-29636	\$2,308.00	
CISCO	WARRANTY FOR 2960 POE 1 YR	04000-29726	\$302.00	
AUDIOCODES	FXO GATEWAY 4-PORT	2213936-1-SR1	\$1,022.00	
AUDIOCODES	FXS GATEWAY 4-PORT	2213938-1-SR1	\$922.00	
AUDIOCODES	GATEWAY SUPPORT, 1YR	04000-00176	\$76.00	
INTEGRATED				
COMM	ICOMM 6911 ALI DATABASE MODEM	RP-6911S	\$1,250.00	
MOTOROLA	MISCELLANEOUS MATERIAL (CABLES, BLOCKS)	RP-MISCMAT	\$500.00	
WESTERN DIGITAL			, , , , , ,	
	NETWORK ATTACHED STORAGE	RP-NAS	\$420.00	
TNT SOFTWARE	REMOTE MONITORING LICENSE, ELM CLASS II	RP-551300	\$92.00	
TNT SOFTWARE	REMOTE MONITORING LICENSE, ELM CLASS I	RP-551200	\$476.00	
CISCO	FIREWALL ASA5506	RP-5506	\$785.00	
VERTIV	LIEBERT GXT4 BATTERY BACKUP	RP-LUPSGXT4	\$3,150.00	
VERTIV	LIEBERT MICROPOD BYPASS SWITCH	RP-LBRT01C	\$470.00	
CYBERPOWER	CP1500 BATTERY BACKUP	RP-CYPR091	\$230.00	
SPECTRACOM	SPECTRACOM NETCLOCK PSAP PKG	RP-NETCLOCKKIT	\$6,600.00	
RPSS				
	ADDITIONAL FIELD ENGINEERING SVCS, PER DAY	RP-LABOR	\$1,000.00	
RPSS	ADDITIONAL TRAINING SERVICES	RP-TRN	\$1,000.00	
EVENTIDE	NEXLOG 740 BASE SYSTEM	RP-NL740	\$7,995.00	
EVENTIDE	ADD BLU-RAY DRIVE TO NEXLOG 740	105385	\$390.00	
EVENTIDE	ADD 2X1 TB RAID 1 STORAGE	108233	\$1,600.00	
EVENTIDE	RACK MOUNT SIDES FOR NEXLOG 740	324430	\$360.00	
EVENTIDE	8 CHANNEL ANALOG CARD FOR NEXLOG 740	105284-008	\$2,700.00	
EVENTIDE	16 CHANNEL ANALOG CARD FOR NEXLOG 740	105284-016	\$4,000.00	
EVENTIDE	INTERNAL IP RECORDING 8 CHANNEL	271052	\$3,850.00	
EVENTIDE	MEDIAWORKS PLUS 8 CONCURRENT USER	271083	\$995.00	

COMPANY NAME	Ryan Public Safety Solutions COMPONENTS LIST		
Provider of	Description of Component	Purchase Part Number	Purchase
Service or		of Component	Cost
Manufacturer of			
Component			
EVENTIDE	911 NENA ANI/ALI SPILL CAD INTEGRATION	209029	\$3,495.00
EVENTIDE	CABLING/CONNECTION KIT FOR NEXLOG 740	RP-VR725-CAB	\$300.00